	Approved For Lease 2002/06/18 : CIA-RDP74B0044 D000100010057-9				
		2359Z 26 FEB 66 TOF SECRET	2 Pla 2 RB	・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・・	
		Constant Expensionals, Constant and September 1970, 19	3 Ala 12	ili aa a een aa aliigi aa aan aan aan ab aan aa aliigi	
25	X1A	DIRECTOR	6 DDSYT	i sa sa manarasa ang	
			3 DIR /cea		
			Comment of the control of the contro		
	WITCH:	342	# ROUTINE		
	enfo i	5/	grantes de de la company de la		
		•			
~ .		TOR 0041Z 27 FEB 66	2 IN 99536		
	X1A X1A	PRIORITY INFO	cne	25X1 <i>A</i>	
25	X,1A [IDEALIST	one.	23/17	
		1. TAPED DEERIEFING OF TANKER CREW NOW COMPLETE. PILOT			
	-	DEBRIEFING HELD SHORTLY AFTER HE WAS RETURNED		25X1A	
	-	BASE HELICOPTER AND SQUADRON DOCTOR. HQS, [
		FERSONNEL PARTICIPATED IN ALL DEBRIEFING. EYEWITNESS REPORTS FROM			
	The state of the s				
	TANKER CREW VERIFY PREVIOUS FINDINGS. FROM ALL REPORTS PULL				
		UP AND BANK AFTER WHAT WAS DESCRIBED AS AN EXCEPTIONALLY FINE REFUELING WERE NORMAL FOR U-2. PILOT WAS IN A 20 DEGREE CLIMB AND 20 DEGREES OF BANK AT MOMENT OF DISINTEGRATION (WORD			
		DISINTEGRATION IS TANKER CREW'S TERMINOLOGY	. ACCORDING TO GREW		
		ARTICLE DISINTEGRATED INTO THREE LARGE PIECE	ES (ENGINE,		
		WING AND FUSELAGE) AND NUMEROUS SMALLER PIEC	CES. ALL LIFE		
	And the second s	SUPPORT EQUIPMENT FUNCTIONED NORMALLY. PILO			
	OSCILLATION INSIDE THE COCKPIT BUT ENCOUNTERED NO DIFFICULTY IN ACTIVATING ANY OF THE EJECTION MECHANISM. 2. ENGINE SECTIONS ONLY PARTS THUS FAR LOCATED. SEARCH				
	TREE CO.				
	für sändreget vor i ernebb	HAMPERED BY BAD WEATHER. GROUND SEARCH CONT	INUING. ENGINE		
			GEOUP 1)	

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROMISITED. COLY NO.

TOP SECRET

IN 96556

PAGE TWO

SECTIONS FOUND NENE MILES EAST SOUTHEAST OF TOWN OF LARAINE, WHICH IS APPROX 30 MILES EAST OF BAKERSFIELD, CALIFORNIA.

AREA IS SPARSELY INHABITED AND HAVE HAD NO REPORTS OF AIRCRAFT PARTS BEING FOUND OR ANY ONE HAVING OBSERVED THE INCIDENT EXCEPT A FOREST RANGER WHO HAPPENED TO BE IN THE AREA AND REPORTED HE SAW THE ENGINE HIT THE GROUND.

- 3. HOSPITALIZATION WAS NOT NECESSARY FOR PILOT. APPEARS NO FRACTURES AND OTHER THAN NORMAL ACHES PILOT IN GOOD CONDITION.
 - 4. BASE SUPPORT IN ALL RESPECTS HAS BEEN EXCELLENT.
 END OF MESSAGE

TOP SECRET

